


CLEANROOM PRODUCT

Fabric Color Chart



AP-200-001



AP-200-002



AP-200-003



Cleanroom Booties/ Soft Sole Booties

- Excellent dust control & suitable for clean room application
- Fabric Surface Resistivity 10^6 to 10^9 ohms/sq
- PU or PVC sole
- Resistance to Ground: 10^6 - 10^9 (Dissipative), 10^9 - 10^7 (Conductive)